

Návod na sestavení


šrouby

①		Ø3.5x40	16	ks
②		Ø3.5x35	6	ks
③		Ø3.5x30	8	ks
④		Ø3.5x25	10	ks
⑤		Ø3x16	4	ks


matice

⑥		M6x55	4	ks
---	---	-------	---	----


držák

⑦		1	ks
---	---	---	----


A




B




C




D




E




F



G



H



(2) ks


I




J




K




L




M




N




O



P




Q




(2) ks


Návod na sestavení

krok 1




①  $\varnothing 3.5 \times 40$ 16 ks

krok 2




②  $\varnothing 3.5 \times 35$ 2 ks

krok 3



②  $\varnothing 3.5 \times 35$ 4 ks
⑥  M6x55 4 ks

krok 4



③  $\varnothing 3.5 \times 30$ 8 ks
④  $\varnothing 3.5 \times 25$ 10 ks
⑤  $\varnothing 3 \times 16$ 4 ks